


Figure 1: Location of the Study Area - Ajax Road, Altona, Victoria



Biosis Pty Ltd
Ballarat, Brisbane, Canberra, Melbourne,
Sydney, Wangarratta & Wollongong

Matter: 17094
Date: 01 October 2013. Checked By: SGM, Drawn By: pangas
Location: P:\17000s\17094\Mapping\17094_F1_Locality.mxd




Acknowledgement: VicRoads
© State of Victoria, Department of Sustainability and Environment, 2007



Legend

- Study Area
- Contaminated soil

Figure 2: Approximate extent of contaminated soil emplacement, Altona, Victoria



biosis ±
Biosis Pty Ltd
Ballarat, Brisbane, Canberra, Melbourne,
Sydney, Wangaratta & Wollongong

Matter: 17094
Date: 01 October 2013
Checked by: SJM, Drawn by: pangas
Location: P:\17000s\17094\mapping\17094_P2_SoilExtent